

QUEENS HARBOUR MASTER PORTSMOUTH

NAVIGATION WARNING

NAV WARN 35/09

No 2 Bar Buoy Light(Reported Unreliable)

1. No 2 Bar Buoy Light (FL(3)R10s) in position 50 46.691N 001 05.963W is reported unreliable
2. Mariners are advised to exercise caution when navigating in the vicinity of No 2 Bar Buoy.
3. The following Portsmouth NAVWARNS remain in force;34/09,29/09,28/09,25/09,10/09,08/09,06/09,03/09,27/08,60/07,34/06,78/05,10/04

Semaphore Tower
HM Naval Base, Portsmouth.

Queen's Harbour Master
